



**1. Evaluation of the existing**  
The diagram shows the reconstruction of the area, on the lateral corner of the road on the ground floor, stone and perforated path remains a strong and effective with connection.

**2. Storage capabilities**  
Stone masonry, of irregular shape, with different diameters, densely arranged in horizontal courses with staggered joints and with wide spaces. The horizontal mortar joint is approximately 2 cm, in grey colour.

**3. Reconnecting**  
From the program and diagram it is possible to visualize the integration of the lateral built brick wall and the existing one connected by stone masonry.

